

2019 Construction Season Street Resurfacing Program

Street: Sunset Street

Starts: Emerson Street

Ends: Emerson Street

Reasons for inclusion in the Resurfacing Program:

- Poor pavement condition (Rating: 3 out of 10)
- Multiple complaints about poor condition
- Efficiency of Work (Major underground sewer work will be needed in approximately 20-25 years; resurfacing work is needed now and cannot wait until underground work; postponing resurfacing would result in the street being resurfaced again with the underground work when it is still well within it's service life.)
- Unknown date of last resurfacing according to best available records (it's been a long time)

Existing Road Photos:

